

**National Transportation Safety Board
Washington, DC 20594**

Brief of Accident

Adopted 05/28/2002

DCA99MA060							
File No. 11847		06/01/1999		LITTLE ROCK, AR		Aircraft Reg No. N215AA	
						Time (Local): 23:51 CDT	
Make/Model: McDonnell Douglas / MD-82						Fatal	
Engine Make/Model: P&W / JT8D-217C						Serious	
Aircraft Damage: Destroyed						Minor/None	
Number of Engines: 2						Crew	
Operating Certificate(s): Flag Carrier/Domestic						Pass	
Name of Carrier: AMERICAN AIRLINES INC						1	
Type of Flight Operation: Scheduled; Domestic; Passenger Only						10	
Reg. Flight Conducted Under: Part 121: Air Carrier						41	
						88	
Last Depart. Point: DFW, TX						Condition of Light: Night	
Destination: Same as Accident/Incident Location						Weather Info Src: Weather Observation Facility	
Airport Proximity: On Airport						Basic Weather: Instrument Conditions	
Airport Name: ADAMS FIELD						Lowest Ceiling: 5000 Ft. AGL, Overcast	
Runway Identification: 4R						Visibility: 1.00 SM	
Runway Length/Width (Ft): 7200 / 150						Wind Dir/Speed: 280 / 018 Kts	
Runway Surface: Concrete						Temperature (°C): 19	
Runway Surface Condition: Wet						Precip/Obscuration: Rain	
Pilot-in-Command		Age: 48				Flight Time (Hours)	
Certificate(s)/Rating(s)						Total All Aircraft: 10234	
Airline Transport; Multi-engine Land;						Last 90 Days: 54	
Instrument Ratings						Total Make/Model: Unk/Nr	
						Total Instrument Time: UnK/Nr	

The full report (NTSB/AAR-01-02) is available on the NTSB Web site. See <http://www.nts.gov/Publictn/publictn.htm> for details.

On June 1, 1999, at 2350:44 central daylight time, 1 American Airlines flight 1420, a McDonnell Douglas DC-9-82 (MD-82), N215AA, crashed after it overran the end of runway 4R during landing at Little Rock National Airport in Little Rock, Arkansas. Flight 1420 departed from Dallas/Fort Worth International Airport, Texas, about 2240 with 2 flight crewmembers, 4 flight attendants, and 139 passengers aboard and touched down in Little Rock at 2350:20. After departing the end of the runway, the airplane struck several tubes extending outward from the left edge of the instrument landing system (ILS) localizer array, located 411 feet beyond the end of the runway; passed through a chain link security fence and over a rock embankment to a flood plain, located approximately 15 feet below the runway elevation; and collided with the structure supporting the runway 22L approach lighting system. The captain and 10 passengers were killed; the first officer, the flight attendants, and 105 passengers received serious or minor injuries; and 24 passengers were not injured.² The airplane was destroyed by impact forces and a postcrash fire. Flight 1420 was operating under the provisions of 14 Code of Federal Regulations (CFR) Part 121 on an instrument flight rules (IFR) flight plan.

Brief of Accident (Continued)

DCA99MA060				
File No. 11847	06/01/1999	LITTLE ROCK, AR	Aircraft Reg No. N215AA	Time (Local): 23:51 CDT

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

1. (C) FLIGHT INTO KNOWN ADVERSE WEATHER - CONTINUED - FLIGHTCREW
2. (F) FATIGUE - FLIGHTCREW
3. (C) IMPROPER DECISION - FLIGHTCREW
4. (F) PROCEDURES/DIRECTIVES - NOT COMPLIED WITH - FLIGHTCREW
5. (F) IMPROPER USE OF PROCEDURE - FLIGHTCREW

Occurrence #2: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

6. (C) SPOILER EXTENSION - NOT VERIFIED - FLIGHTCREW
7. (F) REVERSERS - EXCESSIVE - FLIGHTCREW
8. (F) IMPROPER USE OF EQUIPMENT/AIRCRAFT - FLIGHTCREW

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Findings

9. (F) OBJECT - APPROACH LIGHT/NAVAID

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

The flight crew's failure to discontinue the approach when severe thunderstorms and their associated hazards to flight operations had moved into the airport area and the crew's failure to ensure that the spoilers had extended after touchdown.

Contributing to the accident were the flight crew's (1) impaired performance resulting from fatigue and the situational stress associated with the intent to land under the circumstances, (2) continuation of the approach to a landing when the company's maximum crosswind component was exceeded, and (3) use of reverse thrust greater than 1.3 engine pressure ratio after landing.